O & M Agreements, MRO, LTSAs, Exchange Programs, Complete Overhauls, Outage Support, Reverse Engineering.....

MARINE SERVICES

Utilizing the most advanced cutting edge technologies - Truly independent - Technology neutral



Undersized tail shafts restored.



Pinion Shafts restored.


- Cracked castings 100% effective cold engineered repairs (Engine Blocks, Cyl. Heads, Transmission Housings....)
- Polymer Engineering repairs
- Pintle Housings, Tail Shaft undersize, Tail shaft wrapping (ABS, Bureau VERITAS....approved)
- Engine Blocks, Heads, Turbo Casings and Spindles
- Steam Turbine Cracks and repairs
- Scored Hydraulic Rams and Cylinders
- Restoration of conical or tapered areas
- Pump repairs
- Electric motor sections and conductivity enhancements
- Crankshaft dimensions restoration (Crank Pin, Main). Shot peening to specs if required.
- Material Characterization(s)
- Parts modeling, design, reverse engineering with Solidworks, Inventor, CAD/CAM, Finite Element Analysis, CFD, Virtual Casting simulations.....

To mention a few......

ERMT Copyright 2013 © Contact: <u>info@engrmt.com</u> or <u>engmrt1@gmail.com</u> Mailing address: 470 Broadway No. 354, Bayonne, NJ 07002 <u>www.ENGMRT.com</u> And other strategic locations.

O & M Agreements, MRO, LTSAs, Exchange Programs, Complete Overhauls, Outage Support, Reverse Engineering.....

MARINE SERVICES



Tails shafts dimensioning back to OEM specs at a fractrion of replacement costs.





- Our Engineering and
 Technology portfolio
 includes, but is not limited to
 (always conscious of the best
 alternative to HazMaterials):
- Powder metallurgy
- Plasma transferred weld
- Polymer Engineered repair technologies
- *ESD deposition(dry, wet)*
- 100% effective cold casting repair technologies achieving greater than 100% joint efficiency
- Plating Microfuse_{TM}
- HVOF
- Other innovative technologies
- 3D Modeling
- CAD/CAM
- Reverse Engineering
- Finite Element Analysis
- Professional Engineers on staff
- Metallurgical experts

Among Others......

Pumps restored to better than new OEM Specs.

ERMT Copyright 2013 © Contact: <u>info@engrmt.com</u> or <u>engmrt1@gmail.com</u> Mailing address: 470 Broadway No. 354, Bayonne, NJ 07002 <u>www.ENGMRT.com</u> And other strategic locations.


O & M Agreements, MRO, LTSAs, Exchange Programs, Complete Overhauls, Outage Support, Reverse Engineering.....

MARINE SERVICES





8 MW Marine Engine Block fully restored after cylinder area catastrophic failure.



Hydraulic Rams – Before and After.

ERMT Copyright 2013 © Contact: <u>info@engrmt.com</u> or <u>engmrt1@gmail.com</u>

Mailing address: 470 Broadway No. 354, Bayonne, NJ 07002 <u>www.ENGMRT.com</u>

And other strategic locations.

O & M Agreements, MRO, LTSAs, Exchange Programs, Complete Overhauls, Outage Support, Reverse Engineering.....

MARINE SERVICES



Crankshaft Crankpin damaged and repaired afterwards.



Turbo Wheels and Housings. Oversized Bearing housings restored to OEM specs.



Deck equipment restored to OEM specs.

Minority owned and operated

ERMT Copyright 2013 © Contact: <u>info@engrmt.com</u> or <u>engmrt1@gmail.com</u> Mailing address: 470 Broadway No. 354, Bayonne, NJ 07002 <u>www.ENGMRT.com</u> And other strategic locations.